

Help for the Visually Impaired

Uneven ground, step edges and gradient changes are hazards most of us take for granted in everyday life. We can see them and take the necessary action to stay safe.

Unfortunately for the elderly or visually impaired life is not so simple.


Poles and posts can merge into the background unless clearly marked.



Step edges are another area where the visually impaired are especially at risk.

Unless clearly defined by a bright contrasting colour the step edges become one mass.

They also have great Anti-Slip properties.



Uneven ground and changes in gradient cause their own problems with tripping and stumbling. A bright Yellow outline will clearly identify the hazard, warning pedestrians of the danger. These yellow lines also offer high slip resistance when wet.

For a free no obligation assessment of your facility please

Free Phone : 0800 251 563

Web: www.anti-slip.co.nz

Email: info@anti-slip.co.nz